INSURANCE AND SAFETY FIRE COMMISSIONER'S OFFICE ENFORCEMENT DIVISION

CASE MANAGEMENT SYSTEM

	GA0603900 05322074	floss: 11/08/2005
Case Number:	03322074 County. II will	Bombing
Case Determination	ni.	nined Pending Investigation
Form Numb	er Form/Report Name	Included
ISF-382-6	Preliminary Investigation Report	Included
ISF-6A	Case Narrative	Included
ISF-6B	Incident Diagram	
ISF-6D	Master Name Index/ACAN Report	
101 00	Indictments Warrants Dispositions	
ISF-6E	Photograph Log	Included
131-02	Photos Negatives SCD	Included
ISF-6F	Letter Requesting Insurance Information (O.C.G.A 25-2-33)	
ISF-6G	Voluntary Statement (Not under arrest)	
ISF-6I	Juvenile Rights	
ISF-6J	Voluntary Statement (Under arrest)	
	K9 Report Form	Included
ISF-K9	Confidential Information Release	
ISF-6M	Request for Bank Records	
ISF-6N	Receipt for Property GBI Submission Form	
ISF-299	Receipt for Froperty	
707 010	Laboratory Reports Consent to Search Search Warrant	Included
ISF-310	Miranda Statement	
ISF-327		
ISF-628	Report Release	
(Fire Reports	
	Records Obtained under O.C.G.A. 25-2-33	
	57011	Included
ISF-91	Status Report(s) Active Sciosed	
Signature of Off	Figure Succes Report De	late: 1-31-06
Signature of Oth		,
Reviewed By:	Brian D. Clavier, CFI Dua Clar Off Review De	eate: 01/15/2006 02/10
Reviewed By: ISF 5 (Revised 11/0	Brian D. Clarita, Cr.	ale. 01/13/2000 0

INSURANCE AND SAFETY FIRE COMMISSIONER'S OFFICE ENFORCEMENT DIVISION FIRE INVESTIGATION REPORT

Case Number 05322	.074						
Case Determination	□A	rson	Crimin	nal Attempt to Com	mit Arson		Bombing
	☐Incendiary	Natural	Accidental	⊠Undetermined	Und	etermined Pen	ding Investigation
Property Type Singl	e-occupancy re	sidential			***************************************	Inhabited?	⊠Yes □No
Date and Time Assista	ince Requested	11/08/2005	@ 0715 hours	Date and Tim	ne on Scene	11/08/2005 (a) 1000 hours
Address of Loss 42							
City Ocilla				County Irwin			
Date of Loss 11/08	/2005		Time of Loss	0630 hours	# Injuries	#	Fatalities
Estimated Dollar Loss	\$						
Smoke Detectors Pres	ent?	es No	∐unknown	Smoke Detectors O	perational?	□Yes □	No Unknown
Department Requestir	g Assistance	Irwin County Office	Sheriff's	Person Requesting	Assistance	Sheriff Don	nie Youghn
Name of Business (if	applicable)						
⊠Own	er/Occupant	☐Owner	Оссира	ant Injury	Fata	lity	uspect
Name (Last, First MI)	Miller Be	tty J.					
Date of birth		Social security	number _	Race	White		Sex Female
Address (if different f	rom loss location	on) 10641	Scott Mill Road	Jacksonville, Flori	da		
Insurance Company	Farm Bureau				Tel	ephone229-2	226-0431
Policy NumberF	R-0082936	Coverage: St	ructure:\$111,0	000.00 Conte	nts\$55,000	0.00 Ot	her \$
Owner/Occu	pant 🔲 🖸)wner [Occupant	Juvenile	Injury	Fatality	Suspect
Name (Last, First MI)						
Date of birth	1	Social security	number	Race			Sex
Insurance Company						-	
Policy Number		_ Coverage:	Structure: \$	Co	ontents \$		Other \$
NARRATIVE: The destroyed by fire. Al last two weeks. Also residence. The vehic examination and due	l utilities were destroyed by fi	connected at the ire was a 2000 lichael Lapkfor	e time of the fire Ford Expedition d. The vehicle v	The owner/occupa VIN# IFMEU1765' vas destroyed by fire	ant had not be YLA96532 the. After cond	en living in the lat was located lucting a comp	behind the lete fire scene
This case is closed.							•
A complete report wi	ll be forthcomi	ng.					
Report Submitted By	Vernon S	ingley		Report Review	ved by		
All information conta	nined in this rep	ort is confiden	tial and is not to	be disseminated exc	ept as allowe	ed by law.	
ISF 382-6 Revised 10/06/2							

INSURANCE AND SAFETY FIRE COMMISSIONER'S OFFICE ENFORCEMENT DIVISION CASE NARRATIVE

Case Number:	05322074
Case Number:	05322074

I. DESCRIPTION OF PROPERTY

CONSTRUCTION:

The fire occurred in a one-story structure, being utilized as a single-family dwelling, which was unoccupied at the time of the loss.

The construction of the dwelling consisted of concrete block pillars with a crawl space for the foundation. The exterior walls were constructed of wood studs covered with wood siding. The roof was constructed of wood rafters covered with plywood, tarpaper, and shingles. The interior walls were constructed of wood studs covered with wood. The flooring was constructed with wood two x framing members covered with tongue and groove flooring.

UTILITIES:

Irwin County EMC Power Company provides electrical service within the area. The dwelling was equipped with electrical power at the time of the fire loss. Water service was provided by a private well. The dwelling was not equipped propane gas or natural gas. The dwelling was equipped with an electric heating and cooling system.

II. INVESTIGATION

The investigation commenced on November 8, 2005 and involved an in-depth fire scene investigation

The alarm was received by Irwin County Communications Center. The name of the person that reported the fire is unknown. The Irwin County Fire Department responded to the fire. The weather conditions were clear. Due to the amount of damage to the residence, it was impossible to determine if the doors were secure prior to the fire.

III. FIRE SCENE EXAMINATION

Upon arrival, the scene was not secured by local officials. Yellow crime scene tape had not been installed completely around the fire scene. Legal entry was gained by obtaining a signed Waiver of Rights to a Search Warrant by the legal owner Mrs. Betty Miller. The appropriate documentation can be found in the attachments to this report.

The fire scene examination was begun with a systematic exterior survey of the premises. This systematic exterior examination started on side one and continued in a clockwise direction around the exterior. From the exterior, it was noted that the residence was completely destroyed. The only remnants of the residence were the brick pillars, the fireplace, and the chimney. On the backside of the residence was a 2000 Ford Expedition that was destroyed during the fire. Due to the amount of damage, I was not able to determine if the fire originated at the residence or the vehicle.

Accelerant Detection Canine Cotton examined the scene and made one indication one the ground beside the drivers side of the vehicle. See attached report. Upon closer examination of the area where the canine made the indication it was determined to have been where the gas line from the fuel tank to the engine of the vehicle was located. Samples were not taken.

Where applicable the narrative, and photographs, is included within the attachments of this report to provide a verbal and pictorial representation of the fire scene examination that I conducted.

IV. DETERMINATION

With the information received and the on-scene investigation completed, it is my opinion the cause of this fire is undetermined at this time.

gnature of Officer: Vernor Singley Report Date: 1-31-06
05322074

Signature of Officer

INSURANCE AND SAFETY FIRE COMMISSIONER ENFORCEMENT DIVISION PHOTOGRAPHIC LOG

Case Numb	er: 0532	2074 County: <u>Irwin</u> Date of Loss: <u>11/08/2005</u>			
Photos Taken By: Vernon Singley Date Photos Taken: 11/08/2005					
Photo #	1 thru 7	View of the total destruction of the residence			
Photo #	8 thru 11	View of the exterior of the 2000 Expedition			
Photo #	12	View of the interior of the 2000 Expedition			
Photo #	13	View of the door threshold on the drivers side			
Photo #	14	View of area on the ground where the K-9 indicated possible accelerate			
Photo #	A 11 Other High				
Photo #	19	View of gasoline filter located underneath vehicle			
Photo #	20 & 21	View of the area where gasoline filter was found			
Photo #	22 & 23	View of area where cadaver canine indicated			
Photo #	24 thru 26	View of area where grid lines were placed before sifting debris			
Photo #	27 thru 32	View of area where grid lines were placed after sifting debris			
Photo #					
Photo #					
Photo #					
Photo #					
Photo #					
Photo #					
Photo #					
Photo #					
Photo #					
Photo #					
Photo #					
Photo #					
Photo #					
Photo #					
Photo #					
Photo #					
Photo #					
Photo #					
Photo #					
Photo #					

INSURANCE AND SAFETY FIRE COMMISSIONER'S OFFICE ENFORCEMENT DIVISION

ACCELERANT DETECTION CANINE REPORT

	Fatality
Canine Case #:	County: Irwin
Date of Loss: 11/08/05 Date	and Time on Scene: 11/08/05 @ 10:00 hours
Assistance Requested by: Investigator Vernon Singley	Department: State Fire Marshal's Office
ISF Reference Number: 05322074	Other case number: N/A
K-9 Handler: Bruce Gourley	Canine: Cotton
Owner: Betty J. Miller	Occupant: Betty J. Miller
Address of Loss: Snap Dragon Road Ocilla, Ga.	
Description of loss: Single-occupancy residential	
Was scene secured? No V	Vas consent to search given? Yes
Was search warrant obtained? No -	Weather Conditions on day of scene exam? Clear
	If not, Why? N/A
	1
Were samples taken of these alerts? Yes	If not, Why? N/A
Number of samples taken? 2 Were sample	
If not, Why?	
Samples taken by: Investigator Vernon Singley	Disposition of Samples: Retained By Investigator Vernon Singley
Report released to: Investigator Vernon Singley	Department: State Fire Marshal Investigator
Narrative: The fire occurred in a single-occupancy residential sniffed the interior and exterior of the structure makes	structure and a vehicle. Accelerant Detection Canine, Cotton, ing one indication on the ground beside the driver side door.

INSURANCE AND SAFETY FIRE COMMISSIONER'S OFFICE ENFORCEMENT DIVISION

Suite 708, West Tower, Floyd Building 2 Martin Luther King, Jr. Drive Atlanta, Georgia 30334

NOTICE: You have the right to refuse us entry to search your premises or vehicle. Either a search warrant or your permission must be obtained prior to a search being conducted.

WAIVER OF CONSTITUTIONAL RIGHTS TO A SEARCH WARRANT

(Date) //- 8-05

(Case Number) 05322074

	(City and County) OCILLIA JEWIN
After having been informed of my constitutional rig without a search warrant and of my right to refuse t	whi not to have a search made of the premises or vehicle here-in-after mentioned
Investigator Vernon Singley	
him/her, to conduct a complete search of the below premises	FIRE COMMISSIONER'S OFFICE, and others he/she may designate to assist videscribed premises or vehicle. These agents are authorized by me to take from the
(Address of premises) 425 Si	nap dragon Rd.
the destruction of such items of negligible value samples of fire debris, wood, carpet, soil, paper, pl. This written permission is being given by me to the	ty whatsoever which they deem pertinent to their investigation. I further authorize when such items are no longer of evidentiary value, including but not limited stastic, or glass the above named person(s) voluntarily and without threats or promises of any kind consent to this search without a warrant can and may be used as evidence against may alter the scene including the movement of debris and the collection of evidence
Witnessed by	Signature Signature
	Social security number
	, I
ISF-310	Date of birth
	05322074

INSURAINCE AND SAFETY FIRE COMMISSIONER 5 OFFICE ENFORCEMENT DIVISION CASE STATUS REPORT

Case	Number:	05322074	Case Name	Miller	
			TVE		⊠CLOSED
ACT	IVE CAS	ES:			
	The inves	tigation is continu	ing and the following steps	s are being taken:	
	Explain:	The state of the s		· · · · · · · · · · · · · · · · · · ·	
	Outstandi	ing Warrant(s):			
	Explain:				
	Case pen	ding litigation.			
	New evic	lence has been obt	ained which warrants furth	ner investigation.	-
	Explain:				
	This case	e is being transferre	ed to ISF Investigator.		Case number:
CLO	DSED CA				
	Case has	been adjudicated.	Attach supplemental repo	ort and final court disposition.	
	Exception	onally Cleared			
	Explain:				
П	Acciden	tal Fire			
hand					
\boxtimes	I have in	vestigated this cas	e and have been unable to	obtain sufficient evidence to w	varrant further investigation at this time.
a:			/ 11 1100 - L	Lun lon	Date: /-31-06
Sig	nature of C	nncer:	1		
Rev	viewed By:	Brian D. Clav	ier, CFI LA	Ly Uf I	Date: 01/15/2006